Windows PC Device Setup Instructions

STEP ONE: Install Appropriate Software

1. Visit the Hypersign™ Support Center within Hypersign™+ web portal and download the Windows software.

Note: There is no need to put Hypersign™ in the start up folder because the app installation process will do it for you.

STEP TWO: Update PC Settings

1. Set screen saver to never come on.
2. Turn off all notifications.
3. Set the PC to auto login.
4. Set the PC to "never" for the following power settings:
    - When plugged in, turn off - never.
    - When plugged in, PC goes to sleep after - never.

STEP THREE: Launching & Pairing Hypersign™+

1. When you first launch the Hypersign™ app you will be provided a (6) digital pairing code.
2. Login to the Hypersign™+ web portal and navigate to the device manager:
    - Once in the device manager, click the "Add New Device" button.
    - Insert the pairing code that was provided on the display.
    - Set the device resolution to match the Mac display settings.
    - Name the device, select license types, etc.
    - Once you click submit, a device card is automatically generated.
3. Now your Windows device is paired to your Hypersign™ account, and you can begin publishing your content immediately.

Note: The pairing code is only available for 30 minutes for security purposes and each device will have its own pairing code.